



令和元年度通学路危険箇所シート

事業主体名 (担当課等)	茨城県, 常総警察署		学校区名	豊小学校
図面番号	豊R1-1	路線名	県道野田牛久線	対策箇所 (住所等)
				豊体 地内
状況・危険 な内容等	・朝, 夕, 交通量が多く横断歩道が消えかけているため, 新しく引き直してほしい。 ・ガードレールを学校前だけでなく範囲を長く広げてほしい。			
対策の目的 及び内容 (工事概要等)	茨城県: ガードレール追加可否の検討 常総警察: 速度規制40の路面表示, 横断歩道有りのダイヤモンドマークの表示			



立哨有 (PTA・先生方)


【現状写真】



横断歩道引き直し

つくばみらい市交通安全プログラム

令和元年度通学路危険箇所シート

事業主体名 (担当課等)	茨城県			学区区名	豊小学校
図面番号	豊R1-2	路線名	県道 野田牛久線	対策箇所 (住所等)	豊体 地内
状況・危険 な内容等	歩道が一部途切れている。				
対策の目的 及び内容 (工事概要等)	歩道の整備 茨城県：事業化検討				
対策箇所図	 <p>The map shows the area around Toyouke Elementary School (豊小) and the surrounding residential area. A red line indicates the dangerous spot on the road near the intersection of the main road and a side road. Other landmarks include Toyouke Station (豊体駅), Toyouke City Office (豊体市役所), and various local businesses and houses.</p>				
【現状写真】					
 <p>The left photograph shows a view from the side of the road, looking down the main road. A white van is driving away. The sidewalk is partially cut off, and there are utility poles and trees on the left. The right photograph shows a view from the side of the road, looking towards the dangerous spot. A blue car is driving towards the camera. The sidewalk is partially cut off, and there are utility poles and trees on the right.</p>					